

FEDERAL AVIATION ADMINISTRATION AIRWORTHINESS DIRECTIVES

LARGE AIRCRAFT BIWEEKLY 2012-20

9/24/2012 - 10/7/2012



Federal Aviation Administration
Engineering Procedures Office, AIR-110
P.O. Box 25082
Oklahoma City, OK 73125-0460

Email: rgl@faa.gov

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
Biweekly 2012-01			
2011-18-21	S 2004-26-05	Rolls-Royce plc	Engine: RB211-524B-02, -524B3-02, RB211-524B2, -524B4, -524C2, -524D4, RB211-524G and -524H series
2011-27-03		Boeing	737
2011-27-05	S 2004-12-03	Saab AB, Saab Aerosystems	340A (SAAB/SF340A) and SAAB 340B
2011-27-06		Dassault Aviation	Falcon 7X
Biweekly 2012-02			
2011-25-05		Boeing	767-200, -300, -300F, and -400ER series
2012-01-06		Boeing	767-200 and 767-300 series
2012-01-08		328 Support Services GmbH	328-100 and 328-300
2012-01-09		Boeing	757-200, -200CB, and -300 series
2012-01-10		General Electric	Engine: CF34-10E series
Biweekly 2012-03			
2011-24-04	COR	Boeing	DC-10-10, DC-10-10F, and MD-10-10F
2012-01-04		EADS CASA	CN-235-100, CN-235-200, and CN-235-300
2012-02-03		CFM International S.A.	Engine: CFM56-5B1/3, CFM56-5B2/3, CFM56-5B3/3, CFM56-5B4/3, CFM56-5B5/3, CFM56-5B6/3, CFM56-5B7/3, CFM56-5B8/3, CFM56-5B9/3, CFM56-5B3/3B1, and CFM56-5B4/3B1
2012-02-04		Rolls-Royce plc	Engine: RB211-Trent 553-61, RB211-Trent 553A2-61, RB211-Trent 556-61, RB211-Trent 556A2-61, RB211-Trent 556B-61, RB211-Trent 556B2-61, RB211-Trent 560-61, and RB211-Trent 560A2-61 turbofan
2012-02-07	S 2011-02-07 S 2011-18-01	General Electric	Engine: CF6-45A, CF6-45A2, CF6-50A, CF6-50C, CF6-50CA, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50E, CF6-50E1, CF6-50E2, and CF6-50E2B turbofan
2012-02-08		Aviation Communication & Surveillance Systems LLC	Appliance: See AD
2012-02-09		Boeing	737-100, -200, -200C, and -300 series
2012-02-11	S 2011-11-08	Rolls-Royce plc	Engine: RB211-535E4-37, -535E4-B-37, -535E4-B-75, and -535E4-C-37 turbofan
2012-02-12		Bombardier Inc	DHC-8-400, -401, and -402
2012-03-51	E	Lockheed	P2V
Biweekly 2012-04			
74-08-09 R3	R	Transport Category Airplanes	See AD
2009-11-02	COR	CFM International S.A.	Engine: CFM56-2, CFM56-3, CFM56-5A, CFM56-5B, CFM56-5C, and CFM56-7B series
2012-02-14		Boeing	737-600, -700, -700C, -800, -900, and -900ER series
2012-03-02		Boeing	767-200 and -300 series
2012-03-05		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11
2012-03-09		Boeing	747SP series
2012-03-10		Airbus	A340-642
2012-03-51		Lockheed	P2V
2012-04-01	S 2003-16-18	Rolls-Royce plc	Engine: RB211-Trent 895-17, 892-17, 892B-17, 884-17, 884B-17, 877-17, and 875-17 turbofan
2012-04-05	S 2007-12-07	General Electric Company	Engine: CF6-80C2B1F, CF6-80C2B1F1, CF6-80C2B1F2, CF6-80C2B2F, CF6-80C2B3F, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6F, CF6-80C2B6FA, CF6-80C2B7F, and CF6-80C2B8F turbofan
Biweekly 2012-05			
2012-02-15	S 2007-03-01	Boeing	757-200, -200PF, -200CB, and -300 series
2012-02-17		Boeing	757-200, -200PF, -200CB, and -300 series
2012-02-18		Dassault	MYSTERE-FALCON 50
2012-03-03		Fokker	F.27 Mark 050, F.28 Mark 0070 and 0100
2012-03-08	S 2006-14-05	Bombardier	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900)
2012-03-12		GE	Engine: CF6-80C2 turbofan

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
2012-04-02		Bombardier	CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705); and CL-600-2D24 (Regional Jet Series 900)
2012-04-04		Pratt & Whitney Division	Engine: PW4050, PW4052, PW4056, PW4060, PW4060A, PW4060C, PW4062, PW4062A, PW4152, PW4156, PW4156A, PW4158, PW4160, PW4460, PW4462, and PW4650 turbofan
2012-04-06		328 Support Services GmbH	328-100
2012-04-07		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343; A340-211, -212, -213, -311, -312, and -313
2012-04-08		Bombardier	DHC-8-102, -103, -106, -201, -202, -301, -311, -315; DHC-8-400, -401, and -402
2012-04-09		Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SP, and 747SR series
2012-04-12		Bombardier	CL-600-2B16 (CL -604 Variant)
2012-04-13	S 2011-09-07	Rolls-Royce plc	Engine: RB211-524G2-T-19, -524G3-T-19, -524H-T-36, -524H2-T-19; RB211-Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61 556B2-61, 560-61, 560A2-61; RB211-Trent 768-60, 772-60, 772B-60; RB211-Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17 turbofan
2012-04-14		Rolls-Royce plc	Engine: RB211-Trent 800 turbofan
Biweekly 2012-06			
2012-02-01		Pratt & Whitney	Engine: PW2037, PW2037(M), and PW2040 turbofan
2012-04-11	S 97-22-13	Airbus	A318-111, -112, -121, -122; A319-111, -112, -113, -114, -115, -131, -132, -133; A320-111, -211, -212, -214, -231, -232, -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2012-04-15	S 2007-05-17	Pratt & Whitney	Engine: JT9D-3A, -7, -7A, -7H, -7AH, -7F, -7J, -20J, -59A, -70A, -7Q, -7Q3, -7R4D, -7R4D1, -7R4E, -7R4E1, -7R4E4, -7R4G2, and -7R4H1 series turbofan
2012-05-03		Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2012-05-04		Boeing	767-200, -300, -300F, and -400ER series
2012-05-05		Bombardier	CL-215-1A10, CL-215-6B11 (CL-215T Variant), and CL-215-6B11 (CL-415 Variant)
2012-05-07		Bombardier	DHC-8-102, -103, and -106
2012-05-08		Embraer	ERJ 170-100 LR, -100 STD, -100 SE., -100 SU; ERJ 170-200 LR, -200 SU, and -200 STD
2012-06-01		Cessna	560XL
2012-06-02		Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325
2012-06-04		Bombardier	DHC-8-400, -401, and -402
2012-06-05		Bombardier	DHC-8-400, -401, and -402
2012-06-07	S 2010-17-02	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, A340-541 and -642
2012-06-08		Airbus	A340-211, -212, -311, and -312
2012-06-14		Pratt & Whitney	Engine: JT9D-7R4G2 and -7R4H1 turbofan
2012-06-17		Rolls-Royce Deutschland Ltd	Engine: TAY 611-8 engines, and TAY 611-8C
2012-06-18		Pratt & Whitney	Engine: PW4050, PW4052, PW4056, PW4060, PW4060A, PW4060C, PW4062, PW4062A, PW4152, PW4156, PW4156A, PW4158, PW4160, PW4460, PW4462, and PW4650 turbofan

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
Biweekly 2012-07			
2012-04-11	COR S 97-22-13 S 2002-10-06	Airbus	A318-111, -112, -121, -122; A319-111, -112, -113, -114, -115, -131, -132, -133; A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2012-05-02		Boeing	737-600, -700, -700C, -800, and -900 series
2012-05-06	S 95-20-04 R1	Lockheed Martin	L-1011-385-1, L-1011-385-1-14, L-1011-385-1-15, and L-1011-385-3
2012-06-03		Bombardier	BD-100-1A10 (Challenger 300)
2012-06-06		Boeing	757-200, -200PF, -200CB, and -300 series
2012-06-10	COR	Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-541 and -642
2012-06-11		Airbus	A321-131, -211, -212, and -231
2012-06-12		Airbus	A340-642
2012-06-21		Dassault Aviation	Mystere-Falcon 900
2012-06-22		Airbus	A340-541 and -642
2012-06-23	S 2011-08-07	Rolls-Royce plc	Engine: RB211-Trent 875-17, RB211-Trent 877-17, RB211-Trent 884-17, RB211-Trent 884B-17, RB211-Trent 892-17, RB211-Trent 892B-17, and RB211-Trent 895-17 turbofan
2012-06-25	S 2007-23-01	Goodrich	Appliance: See Ad
2012-07-02		Airbus	A340-541 and -642
2012-07-03	S 2009-21-06	328 Support Services GmbH	328-100 and -300
Biweekly 2012-08			
2012-02-16	S 2007-15-10	Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2012-03-04	S 2008-01-05	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325
2012-04-14	COR	Rolls-Royce plc	RB211-Trent 800 turbofan engines
2012-06-09		Lockheed Martin Corporation	382, 382B, 382E, 382F, and 382G
2012-06-19		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, and -313
2012-06-20		Fokker Services B.V.	F.28 Mark 0070 and 0100
2012-07-04		Cessna	680
2012-07-05		Fokker Services B.V.	F.27 Mark 050
2012-07-06		Boeing	777-200, -200LR, -300, -300ER, and 777F series
2012-07-07		Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
Biweekly 2012-09			
2012-06-02	COR	Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F; and A310-203, -204, -221, -222, -304, -322, -324, and -325
2012-07-08	S 2010-11-13	Embraer	ERJ 170-100 LR, -100 STD, -100 SE., and -100 SU; and ERJ 170-200 LR, -200 SU, and -200 STD
2012-08-02		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; and A340-211, -212, -213, -311, -312, -313, -541, and -642
2012-08-03		Airbus	A300 B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; and A300 C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325
2012-08-04		Bombardier	CL-600-2B19 (Regional Jet Series 100 & 440)
2012-08-05		Bombardier	CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900); CL-600-2E25 (Regional Jet Series 1000)
2012-08-07	S 2011-23-06	Sicma Aero Seat	Passenger seat assemblies
2012-08-08		Learjet	45
2012-08-09		Boeing	777-200, -200LR, -300, -300ER, and 777F series
2012-08-10		Bombardier	CL-600-2B16 (CL-604 Variant)
2012-08-11		Bombardier	DHC-8-400, -401, and -402

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
2012-08-12		Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325
2012-08-13		Boeing	777-200 and -300
2012-08-14		Boeing	767-200, -300, -300F, and -400ER series
2012-08-15		Bombardier	CL-600-2B16 (CL-604 Variant)
2012-08-16		Learjet	60
2012-08-17		Boeing	737-100, -200, -200C, -300, -400, and -500 series
2012-09-01		Cessna	560XL
2012-09-02		Airbus	A300 B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203
2012-09-03		Saab	SAAB 2000
Biweekly 2012-10			
2012-01-05	S 2010-23-26	Airbus	A300 B2-1C, B2K-3C, B2-203, B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, and F4-605R
2012-09-04	S 2004-19-06 R1	Boeing	767-200, -300, -300F, and -400ER series
2012-09-05		Fokker Services B.V.	F.28 Mark 0100
2012-09-06		Boeing	737-700 series
2012-09-07		Airbus	A319-111, -112, -132, A320-111, -211, -212, -214, -232, A321-111, -211, -212, and -231
2012-09-08		Boeing	767-200 and -300 series
2012-09-10		Pratt & Whitney Canada	PT6A-38, -41, -42, -42A, -61, -64, -66, -66B, -110, -112, -114, -114A, -121, -135, and -135A series turboprop engines
2012-09-12	S 2005-23-02	Airbus	A319-111, -112, -113, -114, -115, -131, -132, -133, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2012-09-13		Airbus	A330-223F, -243F, -201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, and -313
2012-09-14		Boeing	777-200, -200LR, -300, -300ER, and 777F series
Biweekly 2012-11			
2012-09-09	S 2010-20-07	International Aero Engines AG	V2500-A1, V2525-D5, V2528-D5, V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, and V2533-A5 turbofan engines
2012-10-03	S 90-21-17	The Boeing Company	747-100, 747-100B, 747-200B, 747-200C, 747-200F, 747-300, 747SR, and 747SP series
2012-10-05		Fokker Services B.V.	F.28 Mark 0070 and 0100
2012-10-06		Saab AB, Saab Aerosystems	SAAB 2000
2012-10-07		Bombardier, Inc	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900), CL-600-2E25 (Regional Jet Series 1000)
2012-10-08	S 2011-08-04	Bombardier, Inc	CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900)
2012-10-10		The Boeing Company	Model 777-200, -200LR, -300, -300ER, and 777F series
2012-10-12	S 2008-18-08	Rolls-Royce plc	RB211-Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, 560A2-61, 768-60, 772-60, 772B-60, 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17 turbofan engines
2012-11-01		Rolls-Royce plc	RB211-Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17 turbofan engines
2012-11-06		Gulfstream Aerospace Corporation	G-1159, G-1159A, and G-1159B
2012-11-07		Honeywell International Inc	ALF502L-2C; ALF502R-3; ALF502R-3A; ALF502R-5; LF507-1F; and LF507-1H turbofan engines
Biweekly 2012-12			
2012-11-03		Boeing	777-200, -200LR, -300, -300ER, and 777F series
2012-11-04	S 2005-18-05	Bombardier Inc	CL-215-1A10 (Water Bomber), CL-215-6B11 (CL-215T Variant)
2012-11-11	S 2009-04-12	Boeing	767-200, -300, and -400ER series

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
Biweekly 2012-13			
2012-11-09	S 2011-04-09	Transport category airplanes	See AD
2012-11-15		BAE	4101
2012-12-01	S 2009-02-04	Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F, and A310-203, -204, -221, -222, -304, -322, -324, and -325 CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900)
2012-12-02		Bombardier	737-300, -400, and -500 series
2012-12-04	S 2008-19-03	Boeing	737-100, -200, -200C, -300, -400, and -500 series
2012-12-05	S 2004-09-09	Boeing	
	S 2009-16-14		
2012-12-06		Fokker	F.28 Mark 0070 and 0100
2012-12-07		Fokker	F.28 Mark 0070 and 0100
2012-12-08		Boeing	777-200 and -300 series
2012-12-09		Boeing	717-200
2012-12-12		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes; and A340-211, -212, -213, -311, -312, and -313 airplanes
2012-12-13		BAE	BAe 146-100A, -200A, and -300A; and Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2012-12-14		Boeing	767-200 and -300 series
2012-12-16		Bombardier	DHC-8-400, -401, and -402
2012-12-17		Bombardier	BD-100-1A10 (Challenger 300)
2012-12-18	S 2010-18-03	Dassault	FALCON 7X
2012-12-19		Boeing	777-200, -200LR, and -300ER series
2012-12-22		BAE	BAe 146-100A, -200A, and -300A; and Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2012-13-01		Saab	340A (SAAB/SF340A) and SAAB 340B
2012-13-03		Bombardier	CL-600-2B19 (Regional Jet Series 100 & 440)
2012-13-51		Gulfstream Aerospace LP	G150
Biweekly 2012-14			
2009-07-01 R1		Rolls-Royce Deutschland Ltd & Co KG	BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines
2012-11-14		Pratt & Whitney Canada	PW118, PW118A, PW118B, PW119B, PW119C, PW120, PW120A, PW121, PW121A, PW123, PW123B, PW123C, PW123D, PW123E, PW123AF, PW124B, PW125B, PW126A, PW127, PW127E, PW127F, PW127G, and PW127M turboprop engines
2012-12-03	S 2010-16-07	Rolls-Royce plc	RB211-Trent 970-84, 970B-84, 972-84, 972B-84, 977-84, 977B-84, and 980-84 turbofan engines
2012-13-05		Boeing	777-200, -200LR, -300, -300ER, and 777F series
2012-13-06		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, and F4-622, A300 C4-605R Variant F
2012-13-07		Boeing	737-100, -200, -200C, -300, -400, and -500 series
2012-13-08	S 2006-01-07	Boeing	747-100, 747-100B, 747-200B, 747-200C, 747-200F, 747-400F, 747SR, and 747SP series
2012-13-09		Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
Biweekly 2012-15			
2012-12-08	COR	Boeing	777-200 and -300 series
2012-12-15	S 2008-10-11	Boeing	757-200, -200PF, -200CB, and -300 series
2012-13-02	S 2011-14-07	Pratt & Whitney Division	PW4074 and PW4077 turbofan engines
2012-13-12		Gulfstream Aerospace Corp	G-IV, GIV-X, GV, and GV-SP
2012-13-51		Gulfstream Aerospace LP	G150
2012-14-02	S 2002-19-11	Boeing	767-200 and -300 series
2012-14-03		Boeing	777-200 and -300 series
2012-14-04		Bombardier Inc	DHC-8-101, -102, -103, -106, -201, -202, -301, -311, and -315
2012-14-05		Airbus	A318-111, -112, -121, -122; A319-111, -112, -113, -114, -115, -131, -132, -133; A320-111, -211, -212, -214, -231, -232, and -233
2012-14-13		Airbus	A318-112 -121; A319-111, -112, -115, -132, -133; A320-214, -232, -233; A321-211, -212, -213, and -231
Biweekly 2012-16			
2011-19-01 R1	R 2011-19-01	Airbus	A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-111, A320-211, A320-212, A320-214, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, and A321-232
2012-15-03		Embraer S.A.	ERJ 190-100 STD, -100 LR, -100 ECJ, and -100 IGW airplanes; and Model ERJ 190-200 STD, -200 LR, and -200 IGW
2012-15-06		Gulfstream Aerospace LP	Astra SPX, 1125 Westwind Astra, and Gulfstream 100
2012-15-09		Airbus	A310-203, -221, and -222
2012-15-10		Boeing	747-400 and 747-400D series
2012-15-11		Dassault Aviation	FALCON 7X
2012-15-12		Boeing	767-200, -300, -300F, and -400ER series
2012-15-13	S 2007-23-18	Boeing	747-100B SUD, 747-300, 747-400, 747-400D series, and 747-200B series
2012-15-14		Airbus	A300 B4-2C, B4-103, B4-203; B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R; and A300 C4-605R Variant F
2012-15-16		Bombardier	DHC-8-102, -103, -106, -201, -202, -301, -311, -315, DHC-8-400, -401, and -402
2012-15-17		Airbus	A300 B4-603, B4-605R, B4-622R; A300 C4-605R Variant F; A300 F4-605R and F4-622R
Biweekly 2012-17			
2012-16-01		Pratt & Whitney Division	See AD
2012-16-05		Airbus	A330-201, -202, -203, -223, and -243; A330-223F and -243F; A340-211, -212, -213, -311, -312, -313, -541, and -642
2012-16-06		Airbus	A300 B4-601, B4-603, B4-620, and B4-622, and A310-203, -204, -221, and -222
2012-16-07		Boeing	737-500 series
2012-16-08		BAE Systems (Operations) Limited	BAe 146-100A, -200A, and -300A, and Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2012-16-09	S 2010-07-04 S 2010-18-01	Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE., and -100 SU; ERJ 170-200 LR, -200 SU, and -200 STD; ERJ 190-100 STD, -100 LR, -100 ECJ, and -100 IGW; and ERJ 190-200 STD, -200 LR, and -200 IGW
2012-16-10		Bombardier, Inc.	DHC-8-400, -401, and -402
2012-16-11		Airbus	A318-112 and -121; A319-111, -112, -115, -132, and -133; A320-214, -232, and -233; and A321-211, -212, -213, and -231
2012-16-12		The Boeing Company	707-100 long body, -200, -100B long body, and -100B short body series; 707-300, -300B, -300C, and -400 series; and 720 and 720B series
2012-16-15		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2012-16-16		The Boeing Company	757-200, -200PF, -200CB, and -300 series

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S - Supersedes

Biweekly 2012-18

2012-15-15	S 2004-09-32	Boeing	757-200, -200CB, and -300 series
2012-16-04		Boeing	777-200 and -300 series
2012-16-14		Honeywell International Inc.	TFE731-20R, -20AR, -20BR, -40, -40AR, -40R, -50R, and -60 turbofan engines
2012-17-01		Goodyear Aviation Tires	Appliance: See AD
2012-17-05		Honeywell International Inc.	TFE731-5 series, TFE731-5AR and -5BR, TFE731-4, -4R, -5AR, -5BR, and -5R series turbofan engines
2012-17-11		BAE SYSTEMS (Operations) Limited	4101
2012-17-12		Boeing	747-400 series
2012-18-03		Pratt & Whitney Division	PW4050, PW4052, PW4056, PW4152, PW4156, PW4650, PW4060, PW4060A, PW4060C, PW4062, PW4062A, PW4156A, PW4158, PW4160, PW4460, and PW4462, , PW4164C, PW4164C/B, PW4168, and PW4168A engines
2012-18-05		Boeing	DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, DC-9-15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, DC-9-32F (C-9A, C-9B), DC-9-41, DC-9-51, DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87), MD-88, MD-90-30

Biweekly 2012-19

2012-04-07	COR	Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes; and A340-211, -212, -213, -311, -312, and -313 airplanes
2012-14-01		Rolls-Royce Deutschland	BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines
2012-17-04		Rolls-Royce plc	RB211-Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17 turbofan engines
2012-17-13		Boeing	707-100 long body, -200, -100B long body, and -100B short body series airplanes; Model 707-300, -300B, -300C, and -400 series airplanes; and 720 and 720B series airplanes
2012-18-11		Bombardier	CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes; CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900) airplanes
2012-18-12		Airbus	A318-111, -112, -121, and -122 airplanes; A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; and A320-111, -211, -212, -214, -231, -232, and -233 airplanes
2012-18-13	S 99-08-23	Boeing	737-100, -200, -200C, -300, -400, and -500 series airplanes
2012-18-14		Pratt & Whitney Canada	PW901A auxiliary power units
2012-18-15		Bombardier	DHC-8-400, -401, and -402 airplanes
2012-18-16		Cessna	750 airplanes
2012-18-17	S 2010-18-13	Pratt & Whitney Division	See AD
2012-19-02	S 2005-25-21	Airbus	A330-243, -243F, -341, -342 and -343 airplanes
2012-19-08		General Electric Company	See AD

Biweekly 2012-20

2012-14-09		Pratt & Whitney Division	PW4050, PW4052, PW4056, PW4152, PW4156, PW4650, PW4060, PW4060A, PW4060C, PW4062, PW4062A, PW4156A, PW4158, PW4160, PW4460, PW4462, PW4164, PW4164C, PW4164C/B, PW4168, PW4168A, PW4164-1D, PW4164C-1D, PW4164C/B-1D, PW4168-1D, PW4168A-1D, and PW4170
2012-18-07		Rolls-Royce plc	RB211-Trent 875-17, RB211-Trent 877-17, RB211-Trent 884-17, RB211-Trent 884B-17, RB211-Trent 892-17, RB211-Trent 892B-17, and RB211-Trent 895-17 turbofan engines
2012-19-03	S 2009-26-17	Boeing	DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, and DC-10-40F airplanes, and Model MD-10-10F and MD-10-30F
2012-19-04	S 94-14-05 S 96-07-06	Fokker Services B.V.	F.28 Mark 0100
2012-19-05		Fokker Services B.V.	F.28 Mark 0070 and 0100
2012-19-06		EMBRAER	EMB-145, -145ER, -145MR, -145LR, -145MP, and -145EP

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
2012-19-07		Airbus	airplanes; and Model EMB-135BJ, -135ER, -135KE, -135KL, and -135LR
2012-19-10		Boeing	A340-541 and -642
2012-19-11		Boeing	777-200, -200LR, -300, -300ER, and 777F series
			737-100, -200, -200C, -300, -400, -500, 737-600, -700, -700C, -800, -900, and -900ER series
2012-20-01		Boeing	737-100, -200, and -200C series
2012-20-03	S 89-15-07	Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series



2012-14-09 Pratt & Whitney Division: Amendment 39-17123; Docket No. FAA-2012-0060; Directorate Identifier 2012-NE-02-AD.

(a) Effective Date

This AD is effective November 7, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the following Pratt & Whitney Division turbofan engines:

(1) PW4000-94" engine models PW4050, PW4052, PW4056, PW4152, PW4156, PW4650, PW4060, PW4060A, PW4060C, PW4062, PW4062A, PW4156A, PW4158, PW4160, PW4460, and PW4462 including models with any dash number suffix.

(2) PW4000-100" engine models PW4164, PW4164C, PW4164C/B, PW4168, PW4168A, PW4164-1D, PW4164C-1D, PW4164C/B-1D, PW4168-1D, PW4168A-1D, and PW4170.

(d) Unsafe Condition

This AD was prompted by reports of 3rd and 4th stage vane fractures in the low-pressure turbine (LPT) of certain PW4000-94" and PW4000-100" turbofan engines. These fractures caused an uncontained engine failure and an LPT case puncture, and resulted in multiple in flight shutdowns. We are issuing this AD to prevent 3rd and 4th stage vane fractures in the LPT, damage to the LPT rotor, uncontained engine failure, and damage to the airplane.

(e) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) At the next LPT overhaul, do the following:

(i) Remove LPT 4th stage vanes that have a P/N listed in Table 1 to paragraph (e) of this AD from service if more than one strip and recoat repair has been performed.

Table 1 to Paragraph (e)–Affected LPT 4th Stage Vane P/Ns

50N174	50N674-01	51N174-001	51N374-001	52N574-01
50N474-01	50N774-01	51N174-002	51N674-01	52N674-01
50N474-001	50N774-001	51N174-003	52N274-01	51N774-01
50N574-01	51N174-01	51N374-01	52N474-01	52N774-01

(ii) Re-assemble the 3rd stage LPT rotor blades by alternating heavy blades next to light blades and balancing blades of similar weights 180 degrees across the rotor.

(iii) Dimensionally examine index 13 through index 34 of the LPT 3rd stage vane cluster assembly. Use Table 2 to paragraph (e) of this AD and Figure 1, Figure 2, and Figure 3 to paragraph (e) of this AD to determine whether the vane is eligible for installation.

Table 2 to Paragraph (e)–Determination of Vane Eligibility

Inspect:	Eligible for Installation Limits:
13	1.820 – 1.830 inches (46.23 – 46.48 mm)
14	1.920 – 1.930 inches (48.77 – 49.02 mm)
15	3.200 inches (81.280 mm) Basic
16	0.900 inch (22.860 mm) Basic
17	0.365 inch (9.271 mm) Basic
18	0.350 inch (8.890 mm) Basic
19	0.160 inch (4.064 mm) Basic
20	0.772 inch (19.609 mm) Basic
21	72° Basic
22	22.382 inch (568.503 mm) Radius – Origin on Plane S Basic
23	21.052 inch (534.721 mm) Radius – Origin on Plane S, concentric with Index 8 Basic
24	Angle from Plane S to Plane SL 3° 4' 37" Basic
25	Angle from Plane S to Plane SM 6° 9' 14" Basic
26	90° Basic for typical airfoil section
27 Distance from rear foot outer diameter surface to airfoil section along Planes S, SL, and SM. For Section B-B: For Section E-E: For Section J-J:	 5.241 inches (133.121 mm) 3.181 inches (80.797 mm) 1.935 inches (49.149 mm)
28 Airfoil chord at Section J-J (1.935 inches (49.149 mm) from rear foot outer diameter surface at Planes S, SL, and SM) At Section E-E (3.181 inches (80.797 mm) from rear foot outer diameter surface at Planes S, SL, and SM)	 1.346 inches (34.188 mm) minimum 1.314 inches (33.376 mm) minimum

At Section B-B (5.241 inches (133.121 mm) from rear foot outer diameter surface at Planes S, SL, and SM)	1.188 inches (30.175 mm) minimum
29	
Airfoil thickness at Section J-J (1.935 inches (49.149 mm) from rear foot outer diameter surface at Planes S, SL, and SM)	0.239 inch (6.071 mm) minimum
At Section E-E (3.181 inches (80.797 mm) from rear foot outer diameter surface at Planes S, SL, and SM)	0.183 inch (4.648 mm) minimum
At Section B-B (5.241 inches (133.121 mm) from rear foot outer diameter surface at Planes S, SL, and SM)	0.139 inch (3.531 mm) minimum
30	
Distance to trailing edge measurement	0.062 inch (1.575 mm)
31	
Airfoil trailing edge thickness	0.030 inch (0.762 mm) minimum
32	
Dimension	0.315 – 0.324 inch (8.001 – 8.230 mm) diameter
33	
Dimension	6.785 – 6.795 inches (172.34 – 172.59 mm)
34	
Dimension	0.692 – 0.714 inch (17.58 – 18.14 mm)

Figure 1 to Paragraph (e) - Determination of Vane Eligibility






Figure 2 to Paragraph (e) - Determination of Vane Eligibility




L-D4520 (0

Figure 3 to Paragraph (e) - Determination of Vane Eligibility

(iv) Dimensionally examine index 23 and index 24 of the vane engagement slots on the rear turbine case, where the 3rd stage vane is installed. Use Table 3 to paragraph (e) of this AD and Figure 4 to paragraph (e) of this AD to determine whether the case is eligible for installation.

Table 3 to Paragraph (e)–Determination of Case Eligibility

Inspect:	Eligible for Installation Limits
23	1.875 inch (47.625 mm) minimum
24	0.097 inch (2.464 mm) minimum

Figure 4 to Paragraph (e) - Determination of Case Eligibility

(v) Inspect the 44 LPT 4th stage vane cluster assemblies P/N 52N774-01 for casting identification "51N554AT 1447 2S1C1" and P/N 52N674-01 for casting identification "51N454AT 655 2S1C1." Remove the vane cluster assembly from service if either of these casting identifications is found.

(2) At the next high-pressure turbine (HPT) overhaul, re-assemble the 2nd stage HPT rotor blades by alternating heavy blades next to light blades and balancing blades of similar weights 180 degrees across the rotor.

(f) Installation Prohibition

After the effective date of this AD, do not install or reinstall into any engine any LPT 4th stage vanes with a P/N listed in Table 1 to paragraph (e) of this AD that are at piece-part exposure and have had more than one strip and recoat repair.

(g) Definitions

(1) For the purpose of this AD, an HPT or LPT overhaul occurs when all disks in the rotor are removed from the engine and the blades are removed.

(2) For the purpose of this AD, piece-part exposure means that the part is removed from the engine and completely disassembled.

(h) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

(i) Related Information

For more information about this AD, contact James Gray, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA; phone: 781-238-7742; fax: 781-238-7199; email: james.e.gray@faa.gov.

(j) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on September 20, 2012.
Diane M. Cook,
Acting Manager, Engine & Propeller Directorate,
Aircraft Certification Service.



2012-18-07 Rolls-Royce plc: Amendment 39-17183; Docket No. FAA-2010-0821; Directorate Identifier 2010-NE-30-AD.

(a) Effective Date

This airworthiness directive (AD) is effective October 29, 2012.

(b) Affected ADs

This AD supersedes AD 2012-06-23 (77 FR 20508, April 5, 2012).

(c) Applicability

This AD applies to Rolls-Royce plc (RR) RB211-Trent 875-17, RB211-Trent 877-17, RB211-Trent 884-17, RB211-Trent 884B-17, RB211-Trent 892-17, RB211-Trent 892B-17, and RB211-Trent 895-17 turbofan engines.

(d) Unsafe Condition

This AD was prompted by the need to add the inspections of the low-pressure (LP) compressor blades listed by serial number (S/N) in Appendices 3H through 3L of Rolls-Royce plc Alert Service Bulletin (ASB) No. RB.211-72-AG244, Revision 4, dated December 22, 2011. We are issuing this AD to prevent multiple LP compressor blades from failing due to blade root cracks, which could lead to uncontained engine failure and damage to the airplane.

(e) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Perform an initial ultrasonic inspection (UI) of the affected LP compressor blades identified by S/N in Appendices 3A through 3L of RR ASB No. RB.211-72-AG244, Revision 4, dated December 22, 2011. Use Table 1 to paragraph (e) of this AD to determine your initial inspection threshold.

Table 1 to Paragraph (e)—Initial Inspection Thresholds

Appendix number of RR ASB Number RB.211-72-AG244, Revision 4, that identifies affected LP compressor blades by S/N	Initial inspection threshold
3A and 3B	Within 70 flight cycles after the effective date of this AD.
3C	Within 10 months after the effective date of this AD.
3D	Within 22 months after the effective date of this AD.
3E	Within 34 months after the effective date of this AD.

3F	Within 46 months after the effective date of this AD.
3G	Within 58 months after the effective date of this AD.
3H	Within 70 months after the effective date of this AD.
3I	Within 82 months after the effective date of this AD.
3J	Within 94 months after the effective date of this AD.
3K	Within 106 months after the effective date of this AD.
3L	Within 118 months after the effective date of this AD.

(2) Thereafter, perform repetitive UIs of the affected LP compressor blades within every 100 flight cycles.

(3) Use paragraph 3.A.(2) of Accomplishment Instructions of RR ASB No. RB.211-72-AG244, Revision 4, dated December 22, 2011, and paragraphs 1. through 3.B. of Appendix 1 of that ASB, or paragraphs 3.B.(3) of Accomplishment Instructions of RR ASB No. RB.211-72-AG244, Revision 4, dated December 22, 2011, and paragraphs 1. through 3.C. of Appendix 2 of that ASB, to perform the UIs. Prior to inspecting the blades per paragraph 3.B.(3) of the Accomplishment Instructions remove the air intake fairing/spinner and spinner extension and annulus fillers.

(4) Do not return to service any engine with blades that failed the inspection required by this AD.

(5) For blades that are removed from the engine and pass inspection, re-apply dry film lubricant before re-installing the blades.

(f) Installation Prohibition

After the effective date of this AD, do not install any affected LP compressor blade that has reached the initial inspection threshold in Table 1 to paragraph (e) of this AD, unless it has passed the UI required by this AD.

(g) Credit for Previous Actions

You may take credit for the initial inspection that is required by paragraph (e)(1) of this AD if you performed the initial inspection before the effective date of this AD using RR ASB No. RB.211-72-AG244, dated August 7, 2009; RR ASB No. RB.211-72-AG244, Revision 1, dated January 26, 2010; RR ASB No. RB.211-72-AG244, Revision 2, dated August 18, 2011; RR ASB No. RB.211-72-AG244, Revision 3, dated December 13, 2011; or RR RB.211-72-E175, Revision 7, dated April 11, 2011.

(h) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

(i) Related Information

(1) For more information about this AD, contact Alan Strom, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7143; fax: 781-238-7199; email: alan.strom@faa.gov.

(2) Refer to European Aviation Safety Agency AD 2012-0025, dated February 8, 2012, for related information.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Rolls-Royce plc Alert Service Bulletin No. RB.211-72-AG244, Revision 4, including appendices 1, 2, and 3A through 3L, dated December 22, 2011.

(ii) Reserved.

(3) For service information identified in this AD, contact Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, England, DE248BJ, phone: 011-44-1332-242424; fax: 011-44-1332-245418; email: http://www.rolls-royce.com/contact/civil_team.jsp.

(4) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal-register/cfr/ibr_locations.html.

Issued in Burlington, Massachusetts, on August 29, 2012.

Colleen M. D'Alessandro,
Assistant Manager, Engine & Propeller Directorate,
Aircraft Certification Service.



2012-19-03 The Boeing Company: Amendment 39-17198; Docket No. FAA-2012-0327; Directorate Identifier 2011-NM-125-AD.

(a) Effective Date

This airworthiness directive (AD) is effective November 5, 2012.

(b) Affected ADs

This AD supersedes AD 2009-26-17, Amendment 39-16156 (74 FR 69268, December 31, 2009).

(c) Applicability

This AD applies to The Boeing Company Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, and DC-10-40F airplanes, and Model MD-10-10F and MD-10-30F airplanes that have been converted from Model DC-10 series airplanes; certificated in any category; as identified in paragraphs (c)(1) and (c)(2) of this AD, as applicable.

(1) Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011 (for airplanes with extended wing-to-fuselage fillets).

(2) Boeing Service Bulletin DC10-53-111, Revision 7, dated March 16, 2011 (for airplanes with conventional wing-to-fuselage fillets).

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by fuel system reviews conducted by the manufacturer, and our determination that additional actions are necessary to address the identified unsafe condition. We are issuing this AD to reduce the potential of ignition sources inside fuel tanks in the event of a severe lightning strike, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Requirements for Installation or Replacement for Certain Airplanes, With New Service Information

This paragraph restates the installation or replacement requirements of paragraph (g) of AD 2009-26-17, Amendment 39-16156 (74 FR 69268, December 31, 2009), with new service information. For airplanes with manufacturer's fuselage numbers identified in the applicable service

bulletin listed in paragraph (g)(1) of this AD: Within 7,500 flight hours or 60 months after September 7, 2006 (the effective date of AD 2006-16-03, Amendment 39-14703 (71 FR 43962, August 3, 2006)), whichever occurs earlier: Install or replace with improved parts, as applicable, the bonding straps between the metallic frame of the fillet and the wing leading edge ribs, on both the left and right sides of the airplane, in accordance with the Accomplishment Instructions of the applicable service bulletin identified in paragraph (g)(1), (g)(2), or (g)(3) of this AD. After February 4, 2010 (the effective date of AD 2009-26-17), use the applicable service bulletin identified in paragraph (g)(2) or (g)(3) of this AD. After the effective date of this AD, use only the applicable service bulletin identified in paragraph (g)(3) of this AD to do the actions required by this paragraph.

(1) McDonnell Douglas DC-10 Service Bulletin 53-109, Revision 4, dated October 7, 1992 (for airplanes with extended wing-to-fuselage fillets); or McDonnell Douglas DC-10 Service Bulletin 53-111, Revision 3, dated August 24, 1992 (for airplanes with conventional wing-to-fuselage fillets).

(2) Boeing Service Bulletin DC10-53-109, Revision 7, dated March 3, 2009 (for airplanes with extended wing-to-fuselage fillets); or Boeing Service Bulletin DC10-53-111, Revision 6, dated March 3, 2009 (for airplanes with conventional wing-to-fuselage fillets).

(3) Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011 (for airplanes with extended wing-to-fuselage fillets); or Boeing Service Bulletin

DC10-53-111, Revision 7, dated March 16, 2011 (for airplanes with conventional wing-to-fuselage fillets).

(h) Retained Requirements for Installation or Replacement for Certain Other Airplanes, With New Service Information

This paragraph restates the installation or replacement requirements of paragraph (h) of AD 2009-26-17, Amendment 39-16156 (74 FR 69268, December 31, 2009), with new service information. For airplanes with fuselage numbers identified in the applicable service bulletin listed in paragraph (g)(2) of this AD that are not also identified in the applicable service bulletin listed in paragraph (g)(1) of this AD, except for airplanes identified in paragraph (i) or (j) of this AD: Within 7,500 flight hours or 60 months, whichever occurs first after February 4, 2010 (the effective date of AD 2009-26-17), install or replace with improved parts, as applicable, the bonding straps between the metallic frame of the fillet and the wing leading edge ribs, on both the left and right sides of the airplane. Do the actions in accordance with the Accomplishment Instructions of the applicable service bulletin identified in paragraph (g)(2) or (g)(3) of this AD. After the effective date of this AD, use only the applicable service bulletin identified in paragraph (g)(3) of this AD to do the actions required by this paragraph.

(i) Retained Requirements for Strap Repositioning for Certain Airplanes, With New Service Information

This paragraph restates the strap repositioning requirements of paragraph (i) of AD 2009-26-17, Amendment 39-16156 (74 FR 69268, December 31, 2009), with new service information. For Group 1-4, Configuration 3 airplanes, as identified in Boeing Service Bulletin DC10-53-109, Revision 7, dated March 3, 2009: Within 7,500 flight hours or 60 months after February 4, 2010 (the effective date of AD 2009-26-17), whichever occurs first, do the actions specified in paragraphs (i)(1) and (i)(2) of this AD.

(1) Remove two braided bonding straps and install two longer braided bonding straps between the metallic frame of the fillet and the wing leading edge ribs, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-109, Revision 7, dated March 3, 2009; or Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011. After the effective date of this AD, use only Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011, to do the actions required by this paragraph.

(2) Measure the resistance of the previously installed bonding straps and, before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-109, Revision 7, dated March 3, 2009; or Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011. After the effective date of this AD, use only Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011, to do the actions required by this paragraph.

(j) Retained Requirements for Inspection and Corrective Action for Certain Airplanes, With New Service Information

This paragraph restates the inspection requirements of paragraph (j) of AD 2009-26-17, Amendment 39-16156 (74 FR 69268, December 31, 2009), with new service information. For Group 1-2, Configuration 2 airplanes, as identified in Boeing Service Bulletin DC10-53-111, Revision 6, dated March 3, 2009: Within 7,500 flight hours or 60 months after February 4, 2010 (the effective date of AD 2009-26-17), whichever occurs first, do the actions specified in paragraphs (j)(1) and (j)(2) of this AD.

(1) Do a general visual inspection to verify correct installation of the braided bonding straps (one left-hand wing and one right-hand wing) as shown in Sheet 7 in Figure 3 of Boeing Service Bulletin DC10-53-111, Revision 6, dated March 3, 2009, or Boeing Service Bulletin DC10-53-111, Revision 7, dated March 16, 2011; and, before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-111, Revision 6, dated March 3, 2009, or Boeing Service Bulletin DC10-53-111, Revision 7, dated March 16, 2011. After the effective date of this AD, use only Boeing Service Bulletin DC10-53-111, Revision 7, dated March 16, 2011, to do the actions required by this paragraph.

(2) Measure the resistance of the previously installed bonding straps and, before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-111, Revision 6, dated March 3, 2009; or Boeing Service Bulletin DC10-53-111, Revision 7, dated March 16, 2011. After the effective date of this AD, use only Boeing Service Bulletin DC10-53-111, Revision 7, dated March 16, 2011, to do the actions required by this paragraph.

(k) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraphs (g), (h), (i), and (j) this AD, if those actions were accomplished before February 4, 2010 (the effective date of AD 2009-26-17, Amendment 39-16156 (74 FR 69268, December 31, 2009)), using Boeing Service Bulletin DC10-53-111, Revision 5, dated March 19, 2008; or Boeing Service Bulletin DC10-53-109, Revision 6, dated July 10, 2008; as applicable; which are not incorporated by reference.

(l) New Installation and Corrective Actions for Certain Airplanes

Within 7,500 flight hours or 60 months after the effective date of this AD, whichever comes first: Do the applicable actions specified in paragraphs (l)(1) through (l)(6) of this AD, as applicable.

(1) For Group 1-4, Configurations 1 and 2 airplanes, as identified in Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011, except airplanes that are identified in paragraph (g) of this AD: Remove any solid metal bonding straps and install seven new braided bonding straps, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011.

(2) For Group 1-4, Configurations 1 and 2 airplanes, as identified in Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011, that are also identified in paragraph (g) of this AD: Remove any solid metal bonding straps not removed during the actions required by paragraph (g) of this AD and install a 7th new braided bonding strap (paragraph (g) of this AD requires installing 6

straps), in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011.

(3) For Group 1-4, Configuration 3 airplanes, as identified in Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011, except airplanes identified in paragraph (i) of this AD: Do the actions specified in paragraphs (l)(3)(i) and (l)(3)(ii) of this AD.

(i) Replace one strap with new braided bonding strap, inspect to determine the existence of an installed solid metal bonding strap and replace any missing strap and any solid metal bonding strap with a new braided bonding strap, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011.

(ii) Measure the electrical resistance across each bonding joint of the six previously-installed braided strap assemblies and verify that brackets have an acceptable fillet seal, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011. Do all applicable corrective actions before further flight.

(4) For Group 1-4, Configuration 3 airplanes, as identified in Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011, that are also identified in paragraph (i) of this AD: Do the actions specified in paragraphs (l)(4)(i) and (l)(4)(ii) of this AD.

(i) Inspect to determine the existence of an installed solid metal bonding strap and replace any missing strap and any solid metal bonding strap with a new braided bonding strap, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011.

(ii) Measure the electrical resistance across each bonding joint of the six previously-installed braided strap assemblies and verify that brackets have an acceptable fillet seal, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011. Do all applicable corrective actions before further flight.

(5) For Group 1-4, Configuration 4 airplanes, as identified in Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011: Do the actions specified in paragraphs (l)(5)(i) and (l)(5)(ii) of this AD.

(i) Inspect to determine the existence of an installed solid metal bonding strap, and replace any missing strap and any solid metal bonding strap with a new braided bonding strap, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011.

(ii) Measure the electrical resistance across each bonding joint of the six previously-installed braided strap assemblies and verify that brackets have an acceptable fillet seal, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011. Do all applicable corrective actions before further flight.

(6) For Group 1-4, Configuration 5 airplanes, as identified in Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011: Inspect to determine the existence of an installed solid metal bonding strap, and replace any missing strap and any solid metal bonding strap with a new braided bonding strap, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011.

(m) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) AMOCs approved previously in accordance with AD 2006-16-03, Amendment 39-14703 (71 FR 43962, August 3, 2006), are approved as AMOCs for the corresponding provisions of paragraphs (g), (h), (i), and (j) of this AD.

(4) AMOCs approved previously in accordance with AD 2009-26-17, Amendment 39-16156 (74 FR 69268, December 31, 2009), are approved as AMOCs for the corresponding provisions of paragraphs (g), (h), (i), and (j) of this AD.

(n) Related Information

(1) For more information about this AD, contact Samuel Lee, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; phone: 562-627-5262; fax: 562-627-5210; email: Samuel.Lee@faa.gov.

(2) For service information specified in this AD that is not incorporated by reference, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, California 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet>.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on November 5, 2012.

(i) Boeing Service Bulletin DC10-53-109, Revision 8, dated March 10, 2011.

(ii) Boeing Service Bulletin DC10-53-111, Revision 7, dated March 16, 2011.

(4) The following service information was approved for IBR on February 4, 2010 (74 FR 69268, December 31, 2009).

(i) Boeing Service Bulletin DC10-53-109, Revision 7, dated March 3, 2009.

(ii) Boeing Service Bulletin DC10-53-111, Revision 6, dated March 3, 2009.

(5) The following service information was approved for IBR on September 7, 2006 (71 FR 43962, August 3, 2006).

(i) McDonnell Douglas DC-10 Service Bulletin 53-109, Revision 4, dated October 7, 1992.

(ii) McDonnell Douglas DC-10 Service Bulletin 53-111, Revision 3, dated August 24, 1992.

(6) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, California 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet>.

(7) You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(8) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal-register/cfr/ibr_locations.html.

Issued in Renton, Washington, on September 11, 2012.
Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2012-19-04 Fokker Services B.V.: Amendment 39-17199. Docket No. FAA-2012-0589; Directorate Identifier 2012-NM-189-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective November 5, 2012.

(b) Affected ADs

This AD supersedes AD 94-14-05, Amendment 39-8957 (59 FR 35237, July 11, 1994); and AD 96-07-06, Amendment 39-9555 (61 FR 14014, March 29, 1996).

(c) Applicability

This AD applies to Fokker Services B.V. Model F.28 Mark 0100 airplanes; certificated in any category; serial numbers 11257, 11258, 11261, 11262, 11264, 11265, 11266, 11284, 11285, 11287, 11288, 11290, 11292, 11294, 11296, 11298, 11299, 11301, 11302, 11304, 11305, 11307, 11309, 11311, 11315, 11317, 11319, 11320, 11322, 11336, 11339, 11341 through 11344 inclusive, 11347, 11348, 11350, 11351, 11362, 11363, 11364, 11371, 11374, 11375, 11382, 11383, 11384, 11389, 11390, 11394, 11400, 11401, 11409, 11410, 11420 through 11424 inclusive, 11429, 11430, 11431, 11433, 11441 through 11456 inclusive, 11461, 11462, 11463, 11470 through 11475 inclusive, 11477, 11484, 11485, 11486, 11488, 11489, 11496, 11497, 11500, 11503, 11505, 11511, 11512, 11516, 11517, 11518, and 11527.

(d) Subject

Air Transport Association (ATA) of America Code 28: Fuel.

(e) Reason

This AD was prompted by reports that the fuel-balance transfer-valve (FBTV) was inadvertently reactivated after required de-activation measures were undone. We are issuing this AD to prevent fuel starvation and a consequent double-engine flameout, possibly resulting in a forced landing, damage to the airplane, and injury to occupants.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Retained Installation of a Locking Device for the FBTV

This paragraph restates the requirements of paragraph (a) of AD 94-14-05, Amendment 39-8957 (59 FR 35237, July 11, 1994). For airplanes having serial numbers 11443, 11446 through 11449 inclusive, and 11456: Within 30 days after August 10, 1994 (the effective date of AD 94-14-05),

remove the actuator from the FBTV, part number (P/N) 7933141J and install a locking device on the FBTV, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-28-029, Revision 1, dated November 30, 1993.

(h) Retained Inspection and Deactivation

(1) This paragraph restates the requirements of paragraphs (a) and (b) of AD 96-07-06, Amendment 39-9555 (61 FR 14014, March 29, 1996). For airplanes identified in Fokker Service Bulletin SBF100-28-030, Revision 1, dated December 5, 1994: After April 29, 1996 (the effective date of AD 96-07-06), whenever the fuel balance transfer system (FBTS) is used during maintenance, prior to further flight, perform an inspection to verify that the position indicator of the FBTV is in the closed position, in accordance with Fokker Service Bulletin SBF100-28-030, Revision 1, dated December 5, 1994. The inspection requirements of this paragraph must be accomplished until the deactivation required by paragraph (h)(2) of this AD is accomplished.

(i) If the position indicator is in the closed position, no further action is required by this paragraph.

(ii) If the position indicator is in the open position, close the FBTV, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-28-030, Revision 1, dated December 5, 1994.

(2) Within 90 days after April 29, 1996 (the effective date of AD 96-07-06, Amendment 39-9555 (61 FR 14014, March 29, 1996)), deactivate the FBTS in accordance with either Part 2 or Part 3, as applicable, of the Accomplishment Instructions of Fokker Service Bulletin SBF100-28-030, Revision 1, dated December 5, 1994. Accomplishment of the deactivation constitutes terminating action for the repetitive inspection requirements of paragraph (h)(1) of this AD.

(i) New Requirements of This AD

Within 12 months after the effective date of this AD, modify the airplane by installing an FBTV locking device, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-28-066, dated June 30, 2011, which includes the attachments identified in paragraphs (i)(1) through (i)(5) of this AD (* the issue date is not specified on the drawing.)

(1) Fokker Manual Change Notification–Maintenance Documentation MCNM-F100-145, dated June 30, 2011.

(2) Fokker Manual Change Notification–Operational Documentation MCNO-F100-059, dated June 30, 2011.

(3) Fokker Drawing W41190, Sheet 013, Issue P*.

(4) Fokker Drawing W41190, Sheet 014, Issue P*.

(5) Fokker Drawing W41190, Sheet 016, Issue P*.

(j) Prohibited Modification

As of the effective date of this AD, no person may modify any airplane using Fokker Service Bulletin SBF100-28-021, dated September 6, 1991 (specified in European Aviation Safety Agency (EASA) AD 2011-0158, dated August 26, 2011, and is not incorporated by reference in this AD). That service bulletin was cancelled by Fokker Service Bulletin SBF100-28-021, Revision 1, dated June 30, 2011 (not incorporated by reference in this AD).

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if

requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) **Airworthy Product:** For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(l) Related Information

Refer to MCAI EASA Airworthiness Directive 2011-0158, dated August 26, 2011, and the service information specified in paragraphs (l)(1), (l)(2), and (l)(3) of this AD, for related information.

(1) Fokker Service Bulletin SBF100-28-029, Revision 1, dated November 30, 1993.

(2) Fokker Service Bulletin SBF100-28-030, Revision 1, dated December 5, 1994.

(3) Fokker Service Bulletin SBF100-28-066, dated June 30, 2011, which includes the attachments identified in paragraphs (l)(3)(i) through (l)(3)(v) of this AD (* the issue date is not specified on the drawing).

(i) Fokker Manual Change Notification–Maintenance Documentation MCNM-F100-145, dated June 30, 2011.

(ii) Fokker Manual Change Notification–Operational Documentation MCNO-F100-059, dated June 30, 2011.

(iii) Fokker Drawing W41190, Sheet 013, Issue P*.

(iv) Fokker Drawing W41190, Sheet 014, Issue P*.

(v) Fokker Drawing W41190, Sheet 016, Issue P*.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on November 5, 2012.

(i) Fokker Service Bulletin SBF100-28-066, dated June 30, 2011, which includes the attachments identified in paragraphs (m)(3)(i)(A) through (m)(3)(i)(E) of this AD (* the issue date is not specified on the drawing).

(A) Fokker Manual Change Notification–Maintenance Documentation MCNM-F100-145, dated June 30, 2011.

(B) Fokker Manual Change Notification–Operational Documentation MCNO-F100-059, dated June 30, 2011.

(C) Fokker Drawing W41190, Sheet 013, Issue P*.

(D) Fokker Drawing W41190, Sheet 014, Issue P*.

(E) Fokker Drawing W41190, Sheet 016, Issue P*.

(ii) Reserved.

(4) The following service information was approved for IBR on April 29, 1996 (61 FR 14014, March 29, 1996).

(i) Fokker Service Bulletin SBF100-28-030, Revision 1, dated December 5, 1994. (Pages 1 through 3, 5, 8, and 10 of this document are identified as Revision 1, dated December 5, 1994. Pages 4, 6, 7, and 9 of this document are dated August 28, 1994 (original issue).)

(ii) Reserved.

(5) The following service information was approved for IBR on August 10, 1994 (59 FR 35237, July 11, 1994).

(i) Fokker Service Bulletin SBF100-28-029, Revision 1, dated November 30, 1993. (Pages 1 through 3 of this document are identified as Revision 1, dated November 30, 1993. Pages 4 through 7 of this document are dated November 10, 1993 (original issue).)

(ii) Reserved.

(6) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands; telephone +31 (0)252-627-350; fax +31 (0)252-627-211; email technicalservices.fokkerservices@stork.com; Internet <http://www.myfokkerfleet.com>.

(7) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(8) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 11, 2012.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2012-19-05 Fokker Services B.V.: Amendment 39-17200. Docket No. FAA-2012-0593; Directorate Identifier 2011-NM-238-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective October 29, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Fokker Services B.V. Model F.28 Mark 0070 and 0100 airplanes, certificated in any category; serial numbers (S/N) 11340 through 11343 inclusive, 11347, 11348, 11350 through 11356 inclusive, 11359, 11360, 11361, 11367 through 11371 inclusive, 11374 through 11378 inclusive, 11382 through 11385 inclusive, 11387 through 11390 inclusive, 11394 through 11397 inclusive, 11400 through 11423 inclusive, 11425 through 11432 inclusive, 11434 through 11439 inclusive, 11441 through 11453 inclusive, and 11456 through 11585 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical Power.

(e) Reason

This AD was prompted by reports of burned contacts in a certain production break plug and its corresponding receptacle. We are issuing this AD to prevent a high electrical load, which might lead to overheating of the galley power supply wiring and/or the electrical connector and consequent smoke or fire in the galley area, which could result in damage to the airplane and injury to occupants.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Modification

Within 24 months after the effective date of this AD: Modify the galley power supply wiring, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-24-044, dated July 14, 2011, including Fokker Manual Change Notification–Maintenance Documentation MCNM-F100-148, dated July 14, 2011.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(i) Related Information

Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2011-0183, dated September 23, 2011; and Fokker Service Bulletin SBF100-24-044, dated July 14, 2011, including Fokker Manual Change Notification–Maintenance Documentation MCNM-F100-148, dated July 14, 2011; for related information.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Fokker Service Bulletin SBF100-24-044, dated July 14, 2011, including Fokker Manual Change Notification–Maintenance Documentation MCNM-F100-148, dated July 14, 2011.

(ii) Reserved.

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands; telephone +31 (0)252-627-350; fax +31 (0)252-627-211; email technicalservices.fokkerservices@stork.com; Internet <http://www.myfokkerfleet.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 11, 2012.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2012-19-06 Empresa Brasileira de Aeronautica S.A. (EMBRAER): Amendment 39-17201.
Docket No. FAA-2012-0638; Directorate Identifier 2011-NM-266-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective October 29, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-145, -145ER, -145MR, -145LR, -145MP, and -145EP airplanes; and Model EMB-135BJ, -135ER, -135KE, -135KL, and -135LR airplanes; certificated in any category; all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 55, Stabilizers.

(e) Reason

This AD was prompted by a report of a lightning strike hitting an airplane tail boom causing certain rear bulkhead parts to jam an elevator control rod. We are issuing this AD to prevent lightning strikes from causing certain parts to contact the airplane pitch control system, which could reduce airplane controllability.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Actions

Within 5,000 flight hours or 48 months after the effective date of this AD, whichever occurs first: Install or rework, as applicable, metallic diverters and aluminum sheets; modify the light assembly on the tail boom rear movable fairing; and replace the hood assembly with a new hood assembly having part number (P/N) 145-23046-403 and reroute its electrical harness. Do all the actions in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 145LEG-55-0013, dated September 8, 2011 (for Model EMB-135BJ airplanes); or EMBRAER Service Bulletin 145-55-0030, Revision 05, dated July 29, 2011 (for Model EMB-145 and EMB-135, except -135BJ, airplanes).

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone (425) 227-1175; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(i) Related Information

Refer to MCAI Brazilian Airworthiness Directive 2011-11-01, dated November 30, 2011, and the following service information, for related information.

(1) EMBRAER Service Bulletin 145LEG-55-0013, dated September 8, 2011.

(2) EMBRAER Service Bulletin 145-55-0030, Revision 05, dated July 29, 2011.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) EMBRAER Service Bulletin 145LEG-55-0013, dated September 8, 2011.

(ii) EMBRAER Service Bulletin 145-55-0030, Revision 05, dated July 29, 2011.

(3) For service information identified in this AD, contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), Technical Publications Section (PC 060), Av. Brigadeiro Faria Lima, 2170–Putim–12227-901 São Jose dos Campos–SP–BRASIL; telephone +55 12 3927-5852 or +55 12 3309-0732; fax +55 12 3927-7546; email distrib@embraer.com.br; Internet <http://www.flyembraer.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 6, 2012.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2012-19-07 Airbus: Amendment 39-17202. Docket No. FAA-2012-0996; Directorate Identifier 2011-NM-040-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective October 16, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Model A340-541 and -642 airplanes; certificated in any category; all manufacturer serial numbers; weight variant (WV) 000, WV001, WV002, WV003, and WV004.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Reason

This AD was prompted by findings of corrosion and rust traces in the lugs and on the bearing outer surface of the nose landing gear (NLG) during routine maintenance checks. We are issuing this AD to prevent failure of the drag stay lower arm, which could result in NLG collapse and consequent reduced controllability of the airplane during takeoff.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Initial and Repetitive General Visual Inspections/Corrective Action

(1) At the applicable compliance time specified in table 1 to paragraph (g) of this AD: Do a general visual inspection of the drag stay lower arm assembly having part number (P/N) 30-1018002-01 of the NLG at the interface between the arm and the spherical bearing races for corrosion traces, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A340-32-5099, dated September 23, 2010.

Table 1 to Paragraph (g) of This AD—Compliance Time

Age of NLG drag stay lower arm assembly as of the effective date of this AD since its first installation on any airplane, or since last NLG overhaul, or last P/N 30–1018002–01 replacement, whichever occurs latest	Compliance time since first installation of the NLG drag stay lower arm assembly on any airplane, or since last NLG overhaul, or since last P/N 30-1018002–01 replacement, whichever occurs latest
Less than 36 months	Before the accumulation of 45 months.
36 months or more, but less than 45 months	Before the accumulation of 52 months, or within 9 months after the effective date of this AD, whichever occurs first.
45 months or more, but less than 60 months	Before the accumulation of 65 months, or within 7 months after the effective date of this AD, whichever occurs first.
60 months or more, but less than 72 months	Before the accumulation of 75 months, or within 5 months after the effective date of this AD, whichever occurs first.
72 months or more, but less than 84 months	Before the accumulation of 85 months, or within 3 months after the effective date of this AD, whichever occurs first.
84 months or more	Within 1 month after the effective date of this AD.

(2) If no corrosion traces are found during the inspection required by paragraph (g)(1) of this AD: Repeat the inspection thereafter at intervals not to exceed 6 months.

(3) If any corrosion traces are found during any inspection required by paragraph (g)(1), (g)(2), or (g)(4) of this AD: At the applicable time after the inspection specified in table 2 to paragraph (g)(3) of this AD, replace the NLG drag stay lower arm assembly with a new or serviceable assembly, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A340-32-5099, dated September 23, 2010.

Table 2 to Paragraph (g)(3) of This AD—Replacement Compliance Time

As of the date of accomplishing the inspection required by paragraph (g)(1) or (g)(2) of this AD: Age of NLG drag stay lower arm assembly, since its first installation on any airplane, or since last NLG overhaul, or last P/N 30–1018002–01 replacement—	Then, after the inspection, replace—
More than 85 months and on which no inspection has been performed during the last 6 months.	Within 5 flight cycles.
65 months or more but 85 months or less, and on which no inspection has been performed during the last 6 months.	Within 1 month.
More than 64 months and on which an inspection has been performed during the last 6 months.	Within 3 months.
Less than 65 months	Within 3 months.

(4) Within 45 months after each replacement of the NLG drag stay lower arm assembly: Perform the initial inspection required by paragraph (g)(1) of this AD, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A340-32-5099, dated September 23, 2010. Repeat the inspection thereafter at intervals not to exceed 6 months.

(h) Terminating Action

Within 10 years after the effective date of this AD: Replace the NLG drag stay lower arm assembly with a serviceable assembly having improved corrosion protection, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A340-32-5101, dated October 20, 2010. Accomplishing this replacement terminates the inspections required by paragraph (g) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1138; fax (425) 227-1149; Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(j) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2010-0214, dated November 2, 2010, and the service information specified in paragraphs (j)(1) and (j)(2) of this AD, for related information.

(1) Airbus Mandatory Service Bulletin A340-32-5099, dated September 23, 2010.

(2) Airbus Mandatory Service Bulletin A340-32-5101, dated October 20, 2010.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the following service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Mandatory Service Bulletin A340-32-5099, dated September 23, 2010.

(ii) Airbus Mandatory Service Bulletin A340-32-5101, dated October 20, 2010.

(3) For service information identified in this AD, contact Airbus SAS—Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this

material at an NARA facility, call 202-741-6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington on September 12, 2012.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2012-19-10 The Boeing Company: Amendment 39-17205; Docket No. FAA-2012-0424; Directorate Identifier 2011-NM-004-AD.

(a) Effective Date

This AD is effective November 7, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 777-200, -200LR, -300, -300ER, and 777F series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 777-32A0082, dated December 9, 2010.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 32, Landing Gear.

(e) Unsafe Condition

This AD was prompted by heat damage and cracks at the pivot joint location of the main landing gear (MLG) cylinder/truck beam. We are issuing this AD to detect and correct cracking in the MLG center axle and shock strut inner cylinder lugs (pivot joint), which could result in fracture of the MLG pivot joint components and consequent collapse of the MLG.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Lubrication and Inspections

At the applicable compliance times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 777-32A0082, dated December 9, 2010, except as provided by paragraph (i) of this AD: Lubricate the MLG pivot joints; do a detailed inspection of the outer diameter chrome on the center axles of the MLG for chicken-wire cracks, corrosion, and chrome plate distress; do a magnetic particle inspection of the outer diameter chrome on the center axles of the MLG for cracks; and do all applicable related investigative and corrective actions; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 777-32A0082, dated December 9, 2010, except as provided by paragraph (i)(2) of this AD. Repeat the lubrication and inspections thereafter at the applicable interval specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 777-

32A0082, dated December 9, 2010. Do all applicable related investigative and corrective actions before further flight.

(h) Definition

For the purposes of this AD, chicken-wire cracks are defined as cracks that occur when stress created in the chrome deposit during plating are relieved. The cracks are evident in the deposited chrome when viewed from a perpendicular plane as a pattern similar to chicken wire. Crack size can vary with plating conditions.

(i) Exceptions to Service Information

(1) Where Boeing Alert Service Bulletin 777-32A0082, dated December 9, 2010, specifies a compliance time after the original issue date of that service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Where Boeing Alert Service Bulletin 777-32A0082, dated December 9, 2010, specifies use of Royco 11MS grease for the lubrication required by paragraph (g) of this AD, this AD also allows use of MIL-PRF-32014 grease.

(j) Optional Actions for Compliance With Paragraph (g) of This AD

(1) Doing the detailed and magnetic particle inspections in accordance with Part 2 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-32-0080, dated July 10, 2008; or Boeing Special Attention Service Bulletin 777-32-0080, Revision 1, dated April 16, 2009; is considered acceptable for compliance with the inspections of the center axle of the MLG required by paragraph (g) of this AD.

(2) Accomplishment of all applicable actions specified in and in accordance with the Accomplishment Instructions of Boeing Service Bulletin 777-32-0085, dated April 14, 2011, is considered acceptable for compliance with the requirements of paragraph (g) of this AD.

(k) Special Flight Permit

Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the airplane can be modified (if the operator elects to do so), if the flight is operated as a non-revenue flight.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings.

For a repair method to be approved, the repair must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(m) Related Information

For more information about this AD, contact Melanie Violette, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6422; fax: 425-917-6590; email: Melanie.violette@faa.gov.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 777-32A0082, dated December 9, 2010.

(ii) Boeing Service Bulletin 777-32-0085, dated April 14, 2011.

(iii) Boeing Special Attention Service Bulletin 777-32-0080, dated July 10, 2008.

(iv) Boeing Special Attention Service Bulletin 777-32-0080, Revision 1, dated April 16, 2009.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; phone: 206-544-5000, extension 1; fax: 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 19, 2012.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2012-19-11 The Boeing Company: Amendment 39-17206; Docket No. FAA-2011-1411; Directorate Identifier 2011-NM-074-AD.

(a) Effective Date

This AD is effective November 7, 2012.

(b) Affected ADs

None.

(c) Applicability

The Boeing Company airplanes; certificated in any category; as identified in paragraphs (c)(1) and (c)(2) of this AD.

(1) Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, as identified in Boeing Special Attention Service Bulletin 737-21-1164, Revision 1, dated May 17, 2012.

(2) Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes, as identified in Boeing Special Attention Service Bulletin 737-21-1165, Revision 1, dated July 16, 2010, as revised by Boeing Special Attention Service Bulletin 737-21-1165, Revision 2, dated April 30, 2012.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 21; Air Conditioning.

(e) Unsafe Condition

This AD was prompted by the report of a flightcrew not receiving an aural warning during a lack of cabin pressurization event. The failure of the altitude pressure switch prevented the aural warning from sounding when the cabin altitude exceeded 10,000 feet. We are issuing this AD to prevent the loss of cabin altitude warning, which could delay flightcrew recognition of a lack of cabin pressurization, and could result in incapacitation of the flightcrew due to hypoxia (a lack of oxygen in the body), and consequent loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Installation

Within 72 months after the effective date of this AD, install a redundant cabin altitude pressure switch, replace the aural warning module (AWM) with a new or reworked AWM, and change certain wire bundles or connect certain capped and stowed wires, as applicable, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-21-1164, Revision 1,

dated May 17, 2012 (for Model 737-100, -200, -200C, -300, -400, and -500 series airplanes); or Boeing Special Attention Service Bulletin 737-21-1165, Revision 1, dated July 16, 2010, as revised by Boeing Special Attention Service Bulletin 737-21-1165, Revision 2, dated April 30, 2012 (for Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes).

(h) Concurrent Actions

For airplanes identified in Boeing Alert Service Bulletin 737-31A1325, dated January 11, 2010 (for Model 737-100, -200, -200C, -300, -400, and -500 series airplanes); and Boeing Alert Service Bulletin 737-31A1332, Revision 3, dated March 28, 2012 (for Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes): Before or concurrently with accomplishment of the actions specified in paragraph (g) of this AD, as applicable, modify the instrument panels, install light assemblies, modify the wire bundles, and install a new circuit breaker, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-31A1325, dated January 11, 2010 (for Model 737-100, -200, -200C, -300, -400, and -500 series airplanes); or Boeing Alert Service Bulletin 737-31A1332, Revision 3, dated March 28, 2012 (for Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes).

(i) Credit for Previous Actions

(1) This paragraph provides credit for the actions required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD using Boeing Special Attention Service Bulletin 737-21-1165, Revision 1, dated July 16, 2010.

(2) For Group 1 airplanes identified in Boeing Alert Service Bulletin 737-31A1332, Revision 1, dated June 24, 2010; except Groups 24, 25, and 27 through 33 airplanes identified in Boeing Alert Service Bulletin 737-31A1332, Revision 3, dated March 28, 2012: This paragraph provides credit for the corresponding actions required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD, using Boeing Alert Service Bulletin 737-31A1332, Revision 1, dated June 24, 2010, which is not incorporated by reference.

(3) For airplanes identified in Boeing Alert Service Bulletin 737-31A1332, Revision 2, dated August 18, 2011; except airplanes identified in paragraph (i)(4) of this AD, and Groups 24, 25, and 27 through 33 airplanes identified in Boeing Alert Service Bulletin 737-31A1332, Revision 3, dated March 28, 2012: This paragraph provides credit for the corresponding actions required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 737-31A1332, Revision 2, dated August 18, 2011.

(4) For Group 21, Configuration 2 airplanes identified in Boeing Alert Service Bulletin 737-31A1332, Revision 3, dated March 28, 2012: This paragraph provides credit for the corresponding actions required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 737-31A1332, Revision 2, dated August 18, 2011; and provided that those actions in Boeing Service Bulletin 737-21-1171, dated February 12, 2009, were accomplished prior to or concurrently with the actions in Boeing Alert Service Bulletin 737-31A1332, Revision 2, dated August 18, 2011.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the Seattle ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

For more information about this AD, contact Francis Smith, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: (425) 917-6596; fax: (425) 917-6590; email: Francis.Smith@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 737-21-1164, Revision 1, dated May 17, 2012.

(ii) Boeing Special Attention Service Bulletin 737-21-1165, Revision 1, dated July 16, 2010.

(iii) Boeing Special Attention Service Bulletin 737-21-1165, Revision 2, dated April 30, 2012.

(iv) Boeing Alert Service Bulletin 737-31A1325, dated January 11, 2010.

(v) Boeing Alert Service Bulletin 737-31A1332, Revision 1, dated June 24, 2010.

(vi) Boeing Alert Service Bulletin 737-31A1332, Revision 2, dated August 18, 2011.

(vii) Boeing Alert Service Bulletin 737-31A1332, Revision 3, dated March 28, 2012.

(3) For The Boeing Company service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on September 19, 2012.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2012-20-01 The Boeing Company: Amendment 39-17207; Docket No. FAA-2012-0491; Directorate Identifier 2011-NM-265-AD.

(a) Effective Date

This AD is effective November 9, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737-100, -200, and -200C series airplanes; certificated in any category; as identified in Boeing Special Attention Service Bulletin 737-53-1313, dated November 3, 2011.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 53; Fuselage.

(e) Unsafe Condition

This AD was prompted by a report of a severed upper butt strap, and cracks in the forward skin and bonded doubler, on one airplane. We are issuing this AD to prevent cracks at the adjacent mating skins (forward and aft), which could initiate just above stringers S-4R and S-4L; and could grow and result in a decompression event.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Actions for Group 1 Airplanes

For Group 1 airplanes, as identified in Boeing Special Attention Service Bulletin 737-53-1313, dated November 3, 2011: Within 120 days after the effective date of this AD, inspect and modify, as required, using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(h) Actions for Groups 2 and 3 Airplanes

For Groups 2 and 3 airplanes, as identified in Boeing Special Attention Service Bulletin 737-53-1313, dated November 3, 2011: Except as provided by paragraph (i)(1) of this AD, at the applicable times identified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 737-

53-1313, dated November 3, 2011, do the actions specified in paragraphs (h)(1) and (h)(2) of this AD, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-53-1313, dated November 3, 2011, except as provided by paragraph (i)(2) of this AD.

(1) Do one of the inspection options identified in paragraphs (h)(1)(i), (h)(1)(ii), and (h)(1)(iii) of this AD; and do all applicable related investigative and corrective actions. Do all applicable related investigative and corrective actions before further flight.

(i) Inspection Option 1: Do a detailed inspection for cracks of the station (STA) 908 forward and aft skin. Thereafter, repeat the inspection at intervals not to exceed 500 flight cycles until the chemical spot test required by paragraph (h)(2) of this AD is done.

(ii) Inspection Option 2: Do a one-time external low-frequency eddy current (LFEC) inspection for cracks of the STA 908 upper butt strap.

(iii) Inspection Option 3: Do a one-time internal LFEC inspection for cracks of the STA 908 upper butt strap.

(2) Do a chemical spot test of the STA 908 upper butt strap to determine the part material, and do all applicable related investigative and corrective actions. Do all applicable related investigative and corrective actions at the times specified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 737-53-1313, dated November 3, 2011, except as provided by paragraph (i)(1) of this AD. Confirming the upper butt strap is made from 2000 series aluminum terminates the inspections required by paragraph (h)(1) of this AD.

(i) Exceptions to the Service Information

(1) Where Boeing Special Attention Service Bulletin 737-53-1313, dated November 3, 2011, specifies a compliance time "after the original issue date of the service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Where Boeing Special Attention Service Bulletin 737-53-1313, dated November 3, 2011, specifies to contact Boeing for repair instructions: Before further flight, repair using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(j) Terminating Action

Replacing the STA 908 upper butt strap and doing all applicable related investigative and corrective actions, in accordance with Part 4, Part 5, and Part 6, of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-53-1313, dated November 3, 2011, except as provided by paragraph (i)(2) of this AD, terminates the inspections and chemical spot test required by this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings.

For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(l) Related Information

For more information about this AD, contact Wayne Lockett, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: (425) 917-6447; fax: (425) 917-6590; email: wayne.lockett@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 737-53-1313, dated November 3, 2011.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call (425) 227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 21, 2012.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2012-20-03 The Boeing Company: Amendment 39-17209; Docket No. FAA-2012-0492; Directorate Identifier 2010-NM-126-AD.

(a) Effective Date

This airworthiness directive (AD) is effective November 9, 2012.

(b) Affected ADs

This AD supersedes AD 89-15-07, Amendment 39-6267 (54 FR 30009, July 18, 1989).

(c) Applicability

This AD applies to The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes; certificated in any category; as identified in Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by new reports of corrosion damage to the end fittings of the wing landing gear (WLG) support beams, and one report of subsequent cracking in the end fittings. We are issuing this AD to detect and correct corrosion and subsequent cracking in the outboard end fittings, which could result in separation of the fitting and damage to adjacent flight control cables and hydraulic systems and consequent reduced controllability of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Retained Repetitive Inspections With Revised Compliance Times

This paragraph restates the requirements of paragraphs A., B., C., and D., of AD 89-15-07, Amendment 39-6267 (54 FR 30009, July 18, 1989) with revised compliance times. For airplanes identified in Boeing Service Bulletin 747-57-2244, Revision 1, dated July 28, 1988: Prior to the accumulation of 30,000 flight hours or 8 years in service, whichever occurs first; or within the next 14 months after August 22, 1989 (the effective date of AD 89-15-07); whichever occurs later; visually inspect around the fitting lug bushings at the WLG beam outboard end fittings for corrosion, and ultrasonically inspect the WLG beam outboard end fittings for cracks, in accordance with Boeing

Service Bulletin 747-57-2244, Revision 1, dated July 28, 1988. Accomplishing the initial inspections required by paragraph (j) of this AD terminates the inspections required by this paragraph.

(1) If no cracking or corrosion is found, repeat the inspections at intervals not to exceed 18 months until paragraph (j) of this AD has been accomplished.

(2) If cracking is found, prior to further flight, remove the WLG beam outboard fitting, and rework, in accordance with Boeing Service Bulletin 747-57-2244, Revision 1, dated July 28, 1988.

(3) If only corrosion is found, within the next 12 months, rework in accordance with Boeing Service Bulletin 747-57-2244, Revision 1, dated July 28, 1988. The ultrasonic inspections for cracks required by paragraph (g) of this AD must be accomplished at intervals not to exceed 6 months until the rework is accomplished. For any corrosion that is found after the effective date of this AD, the rework must be done before further flight.

(h) Retained Terminating Action

This paragraph restates the requirements of paragraph E., of AD 89-15-07, Amendment 39-6267 (54 FR 30009, July 18, 1989). Terminating action for the inspections required by paragraph (g) of this AD consists of rework of the WLG beam outboard fittings, in accordance with Boeing Service Bulletin 747-57-2244, Revision 1, dated July 28, 1988.

(i) New Compliance Times for This AD

For all the actions identified in paragraphs (j) through (t) of this AD, do the actions at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009. Where paragraph 1.E., "Compliance" of this service bulletin specifies a compliance time relative to the original issue date of the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

(j) New Repetitive Inspections for Groups 1 Through 5 Airplanes

For Groups 1 through 3 airplanes, Configurations 1 and 2; and Groups 4 and 5 airplanes: Do detailed and ultrasonic inspections of the end fittings for cracks and corrosion, in accordance with Part 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(k) New Inspections for No Crack or Corrosion Findings for Groups 1 Through 5 Airplanes

If no crack or corrosion is found during any inspection required by paragraph (j) of this AD, do either of the actions required by paragraph (k)(1) or (k)(2) of this AD.

(1) Repeat the detailed and ultrasonic inspections of the end fittings for cracks and corrosion, in accordance with Part 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(2) Do a detailed inspection of the end fittings for fillet seal damage and for cracks and corrosion, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(i) If no fillet seal damage, crack, or corrosion is found: Repeat the inspection required by paragraph (k)(2) of this AD.

(ii) If any fillet seal damage is found, but no crack or corrosion is found: Remove the fillet seal, and do detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(A) If any crack or corrosion is found: Repair or change the end fitting, in accordance with paragraph (l) of this AD.

(B) If no crack or corrosion is found: Apply corrosion inhibiting compound on each end fitting, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009; and do detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(1) If no crack or corrosion is found: Apply corrosion inhibiting compound on each end fitting, in accordance with Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009, and thereafter repeat the inspections required by paragraph (k)(2)(ii)(B) of this AD.

(2) If any crack or corrosion is found: Repair or change the end fitting, in accordance with paragraph (l) of this AD.

(l) New Repair for Crack or Corrosion Findings for Groups 1 Through 5 Airplanes

If any crack or corrosion is found during any inspection required by paragraph (j) or (k) of this AD: Repair or change the end fitting, in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009. After accomplishing the repair or change in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009, do the applicable actions required by paragraph (p) of this AD.

(m) New Repetitive Inspections and Corrective Actions for Group 6 Airplanes

For Group 6 airplanes: Do a detailed inspection of the end fittings for fillet seal damage and for cracks and corrosion, in accordance with Part 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(1) If no fillet seal damage, crack, or corrosion is found: Do the detailed inspection of the end fittings for fillet seal damage and for cracks and corrosion, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(i) If no fillet seal damage, crack, or corrosion is found: Repeat the detailed inspection required by paragraph (m)(1) of this AD.

(ii) If any fillet seal damage is found, but no crack or corrosion is found: Remove the fillet seal, and do detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(A) If any crack or corrosion is found: Repair or change the end fitting, in accordance with paragraph (n) of this AD.

(B) If no crack or corrosion is found: Apply corrosion inhibiting compound on each end fitting, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009; and do detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(1) If any crack or corrosion is found: Repair or change the end fitting, in accordance with paragraph (n) of this AD.

(2) If no crack or corrosion is found: Apply corrosion inhibiting compound, in accordance with Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009, and thereafter repeat the inspections required by paragraph (m)(1)(ii)(B) of this AD.

(2) If any fillet seal damage is found, but no crack or corrosion is found: Remove the fillet seal, and do detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance

with Part 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(i) If any crack or corrosion is found: Repair or change the end fitting, in accordance with paragraph (n) of this AD.

(ii) If no crack or corrosion is found: Apply corrosion inhibiting compound on each end fitting, in accordance with Part 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009; and do detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(A) If any crack or corrosion is found: Repair or change the end fitting, in accordance with paragraph (n) of this AD.

(B) If no crack or corrosion is found: Apply corrosion inhibiting compound, in accordance with Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009, and thereafter repeat the inspections required by paragraph (m)(2)(ii) of this AD.

(n) New Repair for Group 6 Airplanes

If any crack or corrosion is found during any inspection required by paragraph (m) of this AD: Repair or change the end fitting, in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009. After accomplishing the repair or change in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009, do the applicable actions required by paragraph (r) of this AD.

(o) New Optional Terminating Action for Part 1, Part 2, and Part 3 Inspections

In lieu of doing Part 1, Part 2, or Part 3 inspections required by this AD: Repair or change the end fitting, in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009. After accomplishing the repair or change in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009, do the applicable actions required by paragraphs (p) and (r) of this AD. Doing the repair or change terminates the Part 1, 2, or 3 inspections for that part only of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(p) New Follow-On End Fitting Inspection for Groups 1 Through 5 Airplanes

For Groups 1 through 5 airplanes on which the repair or change specified in Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009, has been done: Do detailed and ultrasonic inspections of the end fittings for cracks and corrosion, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009. If no crack or corrosion is found, do the actions required by either paragraph (p)(1) or (p)(2) of this AD.

(1) Repeat the detailed and ultrasonic inspections of the end fittings for cracks and corrosion required by paragraph (p) of this AD.

(2) Do a detailed inspection of each end fitting for fillet seal damage, cracks, and corrosion, in accordance with Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(i) If no fillet seal damage, crack, or corrosion is found: Repeat the inspection required by paragraph (p)(2) of this AD.

(ii) If any fillet seal damage is found, but no crack or corrosion is found: Remove the fillet seal, and do detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance

with Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(A) If any crack or corrosion is found: Repair or change the end fitting, as required by paragraph (q) of this AD.

(B) If no crack or corrosion is found: Apply corrosion inhibiting compound on each end fitting, in accordance with Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009; and do detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 6 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(1) If any crack or corrosion is found: Repair or change the end fitting, as required by paragraph (q) of this AD.

(2) If no crack or corrosion is found: Apply corrosion inhibiting compound, in accordance with Part 6 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009; and repeat the detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 6 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(q) New Repair for Groups 1 Through 5 Airplanes

If any crack or corrosion is found during any inspection required by paragraph (p) of this AD, repair or change the end fitting, in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(r) New Follow-On End Fitting Inspection for Group 6 Airplanes

For Group 6 airplanes on which the repair or change specified in Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009, has been done: Do a detailed inspection of the end fittings for fillet seal damage, cracks, and corrosion, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(1) If no fillet seal damage, crack, or corrosion is found: Do a detailed inspection of each end fitting for fillet seal damage, cracks, and corrosion, in accordance with Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(i) If no fillet seal damage, crack, or corrosion is found: Repeat the inspection required by paragraph (r)(1) of this AD.

(ii) If any fillet seal damage is found, but no crack or corrosion is found: Do detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(A) If any crack or corrosion is found: Repair or change the end fitting as required by paragraph (s) of this AD.

(B) If no crack or corrosion is found: Apply corrosion inhibiting compound on each end fitting, in accordance with Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009; and repeat the detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 6 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(1) If any crack or corrosion is found: Repair or change the end fitting, in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(2) If no crack or corrosion is found: Apply corrosion inhibiting compound, in accordance with Part 6 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009; and repeat the detailed and HFEC inspections of each end fitting for cracks and

corrosion, in accordance with Part 6 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(2) If any fillet seal damage is found, but no crack or corrosion is found: Do detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(i) If any crack or corrosion is found: Repair or change the end fitting, as required by paragraph (s) of this AD.

(ii) If no crack or corrosion is found: Apply corrosion inhibiting compound on each end fitting, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009; and do detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 6 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(A) If any crack or corrosion is found: Repair or change the end fitting, as required by paragraph (s) of this AD.

(B) If no crack or corrosion is found: Apply corrosion inhibiting compound, in accordance with Part 6 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009; and repeat the detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 6 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(s) New Repair for Group 6 Airplanes

If any crack or corrosion is found during any inspection required by paragraph (r) of this AD, repair or change the end fitting, in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(t) New Optional Action for Part 4, Part 5, and Part 6 Inspections

In lieu of doing Part 4, Part 5, or Part 6 inspections required by this AD: Repair or change the end fitting, in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009. After accomplishing the repair or change in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009, do the applicable actions required by paragraphs (p) and (r) of this AD.

(u) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously in accordance with AD 89-15-07, Amendment 39-6267 (54 FR 30009, July 18, 1989), are approved as AMOCs for the corresponding requirements of this AD.

(v) Related Information

(1) For more information about this AD, contact Bill Ashforth, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: (425) 917-6432; fax: (425) 917-6590; email: bill.ashforth@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1, fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(w) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(ii) Boeing Service Bulletin 747-57-2244, Revision 1, dated July 28, 1988.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 26, 2012.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.